

General Environmental Incident Summary

Incident: 3296 **Date/Time Notice:** 4/18/2014 1605 **DEM Incident No:**
Responsible Party: Triple H Trucking
Date Incident: 4/15/2014 **Time Incident:** 2100 **Duration:** 15 minutes
County: McKenzie **Twp:** 150 **Rng:** 99 **Sec:** 24 **Qtr:** NE
Lat: 47.79793 **Long:** -103.28570 **Method:** Interpolation from map
Location Description: 202 3rd Ave. SW, Watford City, ND 58854 (West Lot)

Submitted By: Leigh Jennings **Affiliation:** Rolfson Oil, LLC, Corporate Couns
Address: 124 E. Fulton St.
Suite 404
City: Grand Rapids **State:** MI **Zip:** 49503

Received By:

Contact Person: Brad
188 Dutch Lane
Bridger, MT 59014

Distance Nearest Occupied Building: 100 **Release Contained:** Yes

Type of Incident: Tank Overflow

Description of Released Contaminant: diesel fuel

Volume Spilled: 860.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: Unknown **Reported to NRC:** Unknown

Cause of Incident:

Driver from Triple H Trucking, LLC was unloading diesel fuel, did not check the tank gauge and valve, and overfilled a tank on Rolfson property. The tank overflowed into containment reservoir, with some spillage outside of reservoir.

Risk Evaluation:

No immediate health risk, potential fire hazard.

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

Most of the fuel was in the containment reservoir. Some fuel overflowed to the ground, impacting soil, potential for water impact, but unlikely as absorbent pads were used and clean up started promptly with Power Fuels and Absorbent.

Action Taken or Planned:

Pig blankets used to stop mist of fuel from going outside of containment reservoir and to soak up any amounts outside of reservoir. Power Fuels called and sucked up excess inside reservoir area. Absorbent called to take care of contaminated soil in and outside of reservoir.

Wastes Disposal Location: Power Fuels and Absorbent will dispose of contaminated material in proper place/method.

Agencies Involved:

Updates

Date: 4/18/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Volume:

Notes:

860-gallon diesel fuel release due to tank overflow at the Rolfson depot in Watford City. There was apparently another report called in to Carl Ness of NDDoH, Division of Waste Management, indicating only a 200-gallon release. Followup is necessary.

Date: 4/23/2014 **Status:** Inspection

Author: Roberts, Kris

Updated Volume:

Notes:

4/23/14 - 09:30 on location. This and two other reported spills were inspected. This spill was in the west facility and was responded to using absorbents, pending further soil removal by contractor of the delivery jobber. NDDoH, Division of Water Quality - Groundwater Program will be informed of further remediation date.